Tawakkal Enterprises

DXF Checklist for CNC Laser Cutting

1. Set the drawing units and check one known dimension at full size.
2. Keep the cut outlines separate from notes, dimensions and any mark or bend lines.
3. Close profiles intended to be cut out. Remove doubled lines and stray points.
4. Check hole sizes, cutout sizes and the smallest detail against the finished-part drawing.
5. Attach a PDF preview and list the material, thickness, quantity and finish required.
6. Flag any fit, edge or tolerance requirements. Ask the cutter to confirm the file before production.

Share your file and quote notes at tawakkalenterprises.pk/request-a-quote/.